INDUSTRIAL ENGINEERING

JANUARY, 1929. TWO SECTIONS (SECTION TWO)

INDEX TO VOLUME 86

January to December, 1928

PAGES BY MONTHS

January	1 to 52
February	53 to 104
March	105 to 164
April	165 to 216
May	217 to 268
June	269 to 328
July	329 to 380
August	381 to 432
September	433 to 484
October	485 to 536
November	537 to 600
December	601 to 652

A

Acceleration, Selecting the method of Automatic (H. D. James), *12.
Accident prevention (see Safety).
Acetylene, oxy- (see Welding).
Air compressors (see Compressors).
Air-conditioning practices (E. L. Hogan), *447.
Air, filtered, as an aid to effective lubrication (Allen F. Brewer), *459.
Alarms (see Signals).
Alternator, reversing d.c. leads on (E. J. Morrissey), (C. O. Von Dannenberg), 319.
Announcements, 4, 8, 370, 446, *559, *632.
Arc Welding (See Welding).
Armatures (see Motor reconnection and repair).

B

Batteries:
——Portable storage battery use and abuse (R. G. Macauley), 611.
Bearings:
——Anti-friction:
Keeping the bearings on the job (S. M. Weckstein), *133.
Load and power tests on anti-friction bearings (S. M. Weckstein), *304.
——Ball:
Ball bearings on lineshafts (F. Schoeffler), *561.
Ball bearings on plain bearing motors (J. H. Gallant), *510.
How much power will ball bearings save on lineshafts (H. R. Reynolds), *62.
——How can bearings be made to run cool? (Samuel Carbat), 421, (Theodore M. Small), *477.
——Solving dust problem on high-speed pulverizer drive, 97.
Belts (see also Motor Drive).
——Best belt for severe drive conditions (William Staniar, *540.
——Care of rubber belting, 210.
——Fasteners to fabric base belts, application of (E.D.F.), 321.
——Increasing pulley diameters made the drive pull the load (Donald A. Hampson). *321.
——Layout of, for waterwheel-driven generator (F. D. Hewlett), (H. D. Fisher), 95.
——Leather belts, quality factors of, for power transmission (Roy C. Moore), *29.
——Overcoming shock and moisture on board mill drive, *322.
——Power belt ratings under unusual operating conditions (R. C. Moore), *389.
——Power transmission system keep pace with production demands, making the (W. Thomson Lees), *581.
——Selection of pulleys and belts (W. E. Warner), (W. F. Schaphorst), 422.
——What causes these to wabble? (P.E.K.), 461.
——Width of belts from alignment chart, determining (K. M. White), *261.
——Wrong and right mechanical power transmission, *555.
Blowers:
——Driving double-purpose, at two speeds (Donald A. Hampson), *98.
Book reviews, 427.
Brakes:
——Magnetic:
The magnetic brakes (C. H. Laabs), *246.
Braking, electric:
——Stop that waste! (J. A. Jackson), *443.
Brushes (see Motor reconnection and repair).
Building for the future (J. W. Millspaugh), *54.
Buildings (see Plant, the).
Buying:
——Sometimes it costs more not to buy, 32.

C

Cables (see also Wire).
——Electric elevator cables, inspection of (Archie L. Forger), 158.
——Rearranging power cables (R. F. Kneeland), *617.
——Suggestions on inspection of elevator cables (Donald A. Hampson), 612.
Census bureau, co-operate with the 32.
Chain belt company building for the future (J. W. Millspaugh), *54.
Chain drive (see also Motor drive).
——Adjustable double-reduction (E. H. Laabs), *47.
——Attention overcomes bad operating conditions (D. I. Wheeler), *98.
Charts (see Records).
Coal (see Handling materials).
Code, history and development, of the plant engineers (K. D. Hamilton), 17.
Coils (see also Motor reconnection and repair).
——Cutting out motor coils preferred to rewinding (W. D. Wilson), 613.
——Location of phase coils in a.c. wave windings (A. C. Roe), *629.
——Magnet, safe operating temperature for H. E. Stafford), 501.
Collector Bar:
——Method of straightening crane collector bar (J. Gratiot), *612.
Communication (see Signals).
Commutators (see Motor reconnection and repair).
Compensators (see under Motor control).
Condensers:
——Capacitors for power factor improvement (R. C. Muir), *76.
Contests, 46, *153.
Control, motor (see Motor control).
Controllers (see Motor control).
Conveyors:
——Assembly conveyors (E. J. Tournier), *191, (D. B. Kift), *360.
——Box-counting device for gravity conveyors (P. T. Van Bibber), *189.
——Chain:
Effective gravity stop for chain conveyor (R. M. Thomas), *426.
Protecting, from paint in spray booth (G. R. Wilson), *258.
——Conveyor and breaking roll driven by one motor, *258.
——Conveyor drive selection, how service dictates (R. F. Emerson), *607.
——Dollars and cents results in straight-line application (Edward J. Tournier), *5.
——Fitting the conveyor to the job (R. F. Emerson), *243.
——Gravity roller, cut handling costs (E. J. Tournier), *301.
——One reason for America's prosperity, *85.
Cards (see Wiring).
Corner, collision-proof for two-way traffic (Elton Sterrett), *300.
Couplings (see also Lineshafts):
——Compensating for installation error in alignment by using couplings (E.D.F.), 210.
——Incorrect mounting of flexible coupling causes trouble, 518.
Cranes (see Handling materials).

D

Diagrams (see Records).
Distribution:
——Combination ground detector and alarm (J. F. Morgan), *517.
——Industrial lubrication, storage and (William G. Ziegler), *73.
——Power distribution, light-drive (H. A. Arey), *544.
——Prevention or first aid? for the distribution system (F. A. Westbrook), *130.
——Reconnecting lighting layout for changed service (H. G. Millican), *375.
——Shooting three-phase, four-wire trouble (Edgar Mawhennie), *516.
——Unattended operation for industrial substations (D. C. West), *330.
——Underground distribution at a glance! *471.
——Underground distribution systems (K. D. Hamilton), *169.
——Will this ground cause trouble? (Edward D. Carter), (C. O. Von Dannenberg), *477.
——Wiring trough (L. R. Bogardus), *249.
——Rearranging power cables (R. F. Kneeland), *617.
Drills, electric:
——Lengthening a drill shank for emergency service (Donald A. Hampson), *259.
——Support for electric drill, *99.
Drum:
——Determine length of rope on a drum (W. F. Schaphorst), *391.
Dusts, dangerous, protecting the worker from (M. E. Clements), *470.

E

Editorial Comment 1, 53, 84, *105, 165, 217, 269, 329, 346, 383, 398, 433, 450, 485, 523, 537, 623.
Elevator:
——Location of elevator motors, (W. J. Neustedter), *319.
Engineers Code, Plant (K. D. Hamilton), 17.
Exciter:
Low voltage on (V. E. Johnson), 208.

F

Factor, power (see Power factor).
Filing (see Records).
Fixtures (see Lighting).
Fire (see also Safety).
——Protection is Fire Prevention, Real Fire (James A. Harte), *25.
Forum, the plant engineer's (F. M. Gibson), *317, *368, 418, *472, *490, *548, *634.
Furnace, electric (see Heating).
Fuses:
——Blowing on transformers, cause of (Ernst Dickinson), (E. E. Sigel), (J. W. Bantau), (Phil D. Comer), *48.
——Grounded fuse clip cause of operating trouble (J. F. Morgan), 158.
——Locate faulty, on three-phase motors (R. B. Turner), 96.
——Minimizing delays with spare fuses (J. D.), 374.

G

Gears (see also Pinions):
——Application of, and speed reducers on motor drives (T. C. Roantree), 98.
——Adding life to gear drives (M. T. Schumb), *111.
Generators:
——Compound winding of d.c. generators (Earl R. Witzel), (N. H. Mailhos), *423.
——Size of equalizer required between (R. W. Drake), 502.
——Trouble in phasing out (E. J. Morrissey), 374.
Gibson, F. M., becomes consulting editor, 217, 252.
Grease (see Lubrication and Oil).

H

Hammer made from pipe fittings, handy soft (S. F. Wilson), *613.
Handling materials (see also Conveyors, Cranes, Hoists, Trucks, etc.):
——Adapting gantry to annealing oven, *315.
——Assembly conveyors (E. J. Tournier), *191.
——Assembly conveyors (D. B. Kift), *360.
——Better drives improve mechanical handling efficiency (E. J. Tournier), *492.
——Bringing the stone crushing plant up-to-date, *79.
——Building materials, what price handling (Edward J. Tournier), *57.
——Continuous process methods multiply maintenance responsibilities (John H. Van Deventer), *270.
——Electric trucks and tractors (C. B. Crockett), *297.
——Gravity roller conveyors cut handling costs (Edward J. Tournier), *301.
——Magnets facilitate handling of steel plates, *157.
——Meat packing plant rivals railroads in its transportation facilities (Harold J. Payne), *82.
——Odd shapes and sizes are no obstacle to mechanical handling (E. J. Tournier), *357.
——One reason for America's prosperity, *85.
——Platform lift trucks (E. J. Tournier), *464.
——Quicker ways of doing things around the plant, *236.
——Replace materials handling equipment (E. J. Tournier), *141.
——Signal flags speed-up materials handling traffic (E. L. Fairall), *606.
——Special platform widens the field of the lift truck (G. E. Squier), *624.
——Special problems in handling materials (E. J. Tournier), *415.
——Tractor-trailer trains afford a flexible system (E. J. Tournier), *614.
Hangers (see Shafts).
Heating:
——Heating and ventilating practices at Ford plants (Fay Leone Faurote), *434.
——Heating the small plant (Charles L. Hubbard), *495.
Pictorial section, *451.
Heating, electric (see also Oven):
——Vitreous enameling in the electric furnace, 394.
Hoists (see Handling materials).

*Indicates illustrated articles

UNIV. OF MINN. LIBRARY

I

Idlers (see under Belts).
"Industrial Engineering":
——Genealogy, 32.
Inspection and maintenance:
——Inspection:
Contest on, *153.
Electric elevator cables, inspection of (Archie L. Forger), 158.
Good plant housekeeping (W. G. Ziegler), *406.
Lineshaft drives, inspecting (Russell H. Bowen), *150.
Painted surfaces (Roy C. Sheeler), *121.
Systematic inspection and service for low pressure fuel oil system (H. L. Schultz), *196.
——Maintenance:
Control equipment, maintenance of (H. D. James), *144.
Commutators and brushes, maintenance of (V. E. Johnson), *365.
——Distribution and storage of industrial lubricants (William G. Ziegler) *73
Give the department a sporting chance, 198.
Lighting maintenance (M. Luckiesh), *113.
——Maintenance:
Maintenance stores (J. S. Murray, (C. L. Shultz), *395.
Nuggets from the junk pile (W. E. Haseltime), 611.
Pipe, valves and fittings, low maintenance of (John J. Harman), *185.
Practices at the Fordson Plant (Fay Leone Faurote), *107.
Save space and maintenance by power drives (H. H. Dalton), *585.
Systematic maintenance keeps motor upkeep down (Frank P. Cook), *591.
Systematic structural maintenance and repair (L. E. Driver), *382, *399.
Upkeep of plant structures (W. G. Ziegler), *127.
Installation (see Motor installation).
Instruments (see Meters).
Interpoles (see under Generators and Motor reconnection and repair).

L

Lamps (see also Lighting):
——Brighten-up the dark days (G. Stanley Taylor), *633.
——Condenser across terminals reduces lamp breakage (Grady H. Emerson), 374.
——Flashing shorten lamp life, does?, 336.
——Good lighting at work in industry, *519.
——Mercury vapor lamps, illumination on a trial basis (H. D. Desh), *194.
——Raising the level of artificial illumination (E. F. Labodie), *524.
——Trends in illumination of industrial plants (Kirk M. Reid), *486.
Lighting (see also Lamps):
——Brighten-up the dark days (G. Stanley Taylor), *533.
——Emergency lighting from current transformer (N. Cook), (Philip N. Emigh), (V. E. Johnson), (Edward D. Carter), 255.
——Good lighting at work in industry, *519.
——High bays, lighting of (Davis H. Tuck), *60.
——How to calculate illumination from a bare lamp, *618.
——Illumination on a trial basis (H. D. Desh), *194.
——Industrial lighting systems (A. W. Kakilty), *337.
——Maintenance lighting (M. Luckiesh), *113.
——Raising the level of artificial illumination (E. F. Labodie), *524.
——Trends in illumination of industrial plants (Kirk M. Reid), *486.
Lightning arresters (L. R. Golladay), *221.
Lineshafts (see Shafts).
Literature (see Book reviews and Trade Literature).
Lubricants (see Lubrication and Oil).
——Industrial, storage and distribution of (William G. Ziegler), *73.
Lubrication:
——A study of the requirements of low-temperature (Allen F. Brewer), *9.
——Filtered air as an aid to effective lubrication (Allen F. Brewer), *459.
——Lubricant for high temperature (M. C. Parker), 500.
——Lubrication pays its way in service to production, *619.
——Modern lubrication practice in the steel mill (Allen F. Brewer), *294.
——Selecting lubricants for new equipment (Allen F. Brewer), *124.

M

Maintenance (see Inspection and).
Materials, handling (see Handling materials).
McGraw, James. H., awarded Bok Gold Medal, *105.
Measurements (see Meters).
Meters:
——Watt-hour, how to determine accuracy of 157.
Motor bearings (see Bearings).
Motor control:
——Auxiliary switches on discharge valves control pump motor circuits (Chas. A. Peterson), *480.
Motor control (Cont.):
——Built-in motors, test practices of Cincinnati Grinders, Inc., on machines having (C. E. Brown), *41.
——Compensator:
Adapting 220-volt to 440-volt (K. M. White), *96.
——Control equipment (H. J. Brown), *627.
——Pumping unit controlled by float switch (Grady H. Emerson), *425.
——Remote control as an aid to production (W. S. Risser), *503.
——Selecting the method of automatic acceleration (H. D. James), *12.
——Stopping motor when pump loses suction (Phil D. Comer), 158.
——What type control for industrial power drives?, *587.
Motor drive (see also Belts, Chains, Clutches, Couplings, Gears, etc):
——Application of gears and speed reducers on motor drives (T. C. Roantree), 98.
——Connecting up silent chain to engine shaft to drive reciprocating pumps, *260.
——Direct drive motors (F. H. Penny), *513.
——Driving adjustable spindle from fixed-position motor (J. E. Winn), *323.
——Fitting the motor to the drive, *572.
——Layout of power drives in forging plant (C. E. Bracken), *569.
——Obtaining half-speed, for special work (E. D. F.), *97.
——Power drives and controls that serve industry, *575.
——Reversing motor drives (J. W. Corey), *362.
——Saving space and maintenance by power drives (H. H. Dalton), *585.
——Short-center drive requirements (A. A. Cushman), *563.
——What type control for industrial power drives?, *587.
Motor reconnection and repair:
——Armature:
Field and armature coils, protecting stored (A. C. Roe), *22.
——Brushes:
Excessive arcing at motor brushes (Wm. McGuire), (R. F. Finch), (W. E. Warner), (Edward A. Gibbs), (H. J. Achee), 209.
——Changing 120-volt series motor to 220-volt, shunt type (Henry Kaelin), 99.
——Coils:
Cutting out coils in emergency repairs to a.c. motors (G. H. Emerson), 260.
Cutting out motor coils preferred to rewinding (W. D. Wilson), 613.
Drying out water-soaked generator coils (Grady H. Emerson), 258.
Laying out and making pulled (A. C. Roe), (D. H. Braymer), $65.
Locating short-circuited coils in a.c. motors (P. Justus), *476; (J. Spitzer), (R. F. Emerson), Walter M. Rennick), 500.
——Commutators:
Commutation (Vinzens Spath), 517.
Commutator assembled (Jesse W. Zimmerman), *455.
Commutator Assembly (Jesse W. Zimmerman), *410.
Defective Commutation, its causes and remedies (V. E. Johnson), *231.
Elements of commutation (V. E. Johnson), *173.
Maintenance of commutators and brushes (V. E. Johnson), *365.
Portable unit for emergency service, *323.
Reverse-phase relays, operation of, *345.
——Demagnetized, how can a motor shaft be (W. M. Price), (Harry E. Reinhold), (Chas. A. Peterson), 256.
——Electrical repair shop and its methods of servicing continuous process equipment (W. A. Beck), *289.
——Heating of, traced to defective soldering (Grady H. Emerson), 516.
——Induction Motors:
Noises, causes and remedy of (A. C. Roe), 99.
——Loose lead caused excessive current demand (W. E. Warner), 157.
——Maintenance keeps upkeep down, systematic (Frank P. Cook), *591.
——Replacing the misfit motors (R. H. Rogers), *117.
——Rewinding (see Winding).
——Solder rotor clips without an iron, how to (Joe F. Winiski), *425.
——Speed:
Changing speed of motor without rewinding (A. C. Roe), 478.
Speed of single-phase motors (Grady H. Emerson), (J. M. Peterson), 255.
——Stator windings for old (L. A. Cole), *385.
——Stop that waste! (J. A. Jackson), *443.
——Trouble:
Automatic starting of motors after failure of power (R. F. Finch), 423.
Compressed air used to remove cause of excessive sparking, 306.
Eliminated by starting motor slowly, 96.
Symptoms and causes of motor troubles and how to remedy them, *89.
Undersized motors on grinder cause of trouble, 261.

*Indicates illustrated articles

Motor reconnection and repair (Cont.):
——Winding:
Bringing obsolete motor windings up to date (A. C. Roe), *311.
Concentric chain windings for open-slot machines (A. C. Roe), *467.
Frequency affect core iron, how does increase in (W. E. Paulsen), 320; (A. C. Roe), 422.
Location of phase coils in a.c. wave windings (A. C. Roe), *629.
Modern coils and windings (A. C. Roe), *343.
Pulled coils, layout and winding of (A. C. Roe), *181.
Rewinding a portable drill armature (Vincent Hurst), 320.
Small coils wound in lathe with inexpensive device, *424.
Stator windings for old (L. A. Cole), *385.
Winding data for old induction motor (E. F. Rogers), (L. C. Anderson), (V. S. Foster), 476.
Motor repair (see Motor reconnection and repair).
Motor starters (see Motor control).
Motor testing (see Motor reconnection and repair).
Motor troubles (see Motor reconnection and repair).
Motors (see also other Motor subjects):
——Synchronous:
Adjustable-speed a.c. motor drive for textile machines, *259.
Control equipment for synchronous motors (D. W. McLenegan), *333.
Electrical equipment for coke plants (R. F. Emerson), *307.

N

New Equipment for Plant Operation and Maintenance *49, *101, *159, *324, *376, *428, *481, *532, *595, *641.

O

Ovens, electric:
——Armature baking ovens, practical pointers on (A. H. Kopprasch), *355
——Melting pots for soft metals (P. H. Clark and A. N. Otis), *177.
——Wanted—an electric oven that would run itself! (J. W. Nicolls), *462.

P

Paint and painting:
——Color for the plant (J. Elmer Housely), *225.
——Cost of interior painting of mill-type building (R. D. Waltz), 47.
——Inspection of painted surfaces (Roy C. Sheeler), *121.
——Maintenance painting on an engineering basis (Roy C. Sheeler), *340.
——Painting program up-to-date, keeping the, *347.
——Preparing insulated pipe for painting (H. E. Stafford), (Chas. A. Peterson), 209.
——Waterproofing concrete wall (W. E. Warner), 319.
Phasing:
——Trouble in Phasing Out, (E. J. Morrissey), 374.
Pictorial Section, *33, *85, *137, *199, *235, *285, *347, *399, *451, *519, *555, *575, *619.
Plant, the:
——Building for the future (J. W. Millspaugh), *54.
——Charting the responsibility of the engineer (Plant Engineers' Club), *69.
——Color for the plant (J. Elmer Housley), *225.
——Upkeep of structures, preparation of (W. G. Ziegler), *127.
Plant engineering department, jurisdicition and conduct of an, 43.
Power distribution, light drive (H. A. Arey), *544.
Power Exposition, Sixth, *39.
Power factor:
——How to correct low power factor (Ottomar H. Henschel), *602.
——Inspection in damp atmosphere cause of condenser failure (W. E. Warner), 257.
——Improvement for power factor (R. C. Muir), *76.
——Relation between coal pile and (B. W. Scott), 422.
Power transmission (see Belts, Chains, Clutches, Couplings, Gears, Motor drive, etc.):
——Ball bearings on lineshafts (F. Schoeffler), *560.
——Belting, chart of power transmission, 552.
——Belt for severe drive conditions, finding the best (William Staniar), *540.
——Control for industrial power drives, what type, *587.
——Fitting the motor to the drive, *572.
——Layout of power drives in a forging plant (C. E. Bracken), *569.
——Light drive power distribution (H. H. Arey), *544.
——Loss reduction in mechanical power transmission (William Staniar), *218.
——Maintenance keeps motor upkeep down, Systematic (Frank P. Cook), *591.
——New in power transmission, what is, 537.
——Power drives and control that serve industry? *575.
——Power transmission system keeps pace with production demands, making the (W. Thompson Lees), *581.

APR 22 '29 U OF M BINDERY

En 620.5
fIn206

Power transmission (Cont.):
——Rights and wrongs of mechanical power transmission, *555.
——Save space and maintenance by revising power drives (H. H. Dalton), *584.
——Short-center drive requirements, study your (A. A. Cushman), *563.
——What to use and where for mechanical power transmission, 550.
Power Transmission Association, the why and wherefore of the (William Staniar), 37.
Protection, motor (see Motor control).
Pulleys:
——Selection of pulleys and belts (W. E. Warner), (W. F. Schaphorst), 422.
Pumps:
——Automatic pump control (L. S. Monroe), *527.
——Centrifugal, raising hot water with (W. E. Warner), 502.
——Pump selection, how service requirements influence (E. J. Gealy), *227.
Purchasing (see Buying).

Q

Questions Asked and Answered, *47, *93, 207, 253, 318, *371, 420, 475, 499, 565, *636.

R

Records:
——Plant Engineer, charting the responsibility of the (Plant Engineers' Club), *69.
Repair shop, electrical (C. H. Munch), *392.
Repairs (see Motor reconnection and repair).
Respiration, artificial (see Safety).
Rewinding (see Motor reconnection and repair).
Rope:
——Determine length of rope on a drum (W. F. Schaphorst), *391.
——How wire rope should be unreeled or uncoiled to prevent kinks, 512.
Rotors (see Motor reconnection and repair).

S

Safety:
——Armco uses safety flags, *414.
——Distribution system, prevention or first aid for the (F. A. Vastbrook), *130.
——Exit, which will you choose? *137.
——First aid for eye injuries, 248.
——Protection is fire prevention, real fire (James A. Harte), *25.
——Safeguarding men in the plant, *138.
——Safety, how Armco trains its men to think and act (Hall Packer), *281.
Sanitation:
——Good housekeeping (W. G. Ziegler), *406.
Shafts and Shafting:
——Ball bearings on lineshafts cut operating costs (F. Schoeffler), *561.
——Ball bearings save power on lineshafts (H. R. Reynolds), *62.
——Inspecting lineshaft drives (Russell H. Bowen), *150.
Shank extension for deep-hole drilling (Garrett White), *480.
Shops (see Motor reconnection and repair and Plants).
Signals:
——Combination ground detector and alarm (J. F. Morgan), *517.
Signals (Cont.):
——Low-water alarm on depth board, construction details of (E. J. Morrisey), *158.
Speed control (see Motor control, Motor reconnection and repair and Speed reducers).
Speed reducers:
——Application of gears and, on motor drives (T. C. Roantree), 98.
Starters (see Motor control).
Stator (see Motor reconnection and repair).
Stockkeeping:
——Maintenance stores (J. S. Murray), (C. L. Shultz), *395.
Storage:
——Industrial Lubricants, distribution and (William G. Ziegler), *73.
——Storekeeping methods for maintenance tools and supplies (H. C. Dent), *147.
Storage batteries (see Batteries).
Structures:
——What Preparation for the Upkeep of Plant Structures? *127.
Substations:
——Unattended operation for industrial substations (D. C. West), *330.
Switchboard (see also Switches).
——Transite barrier support for inclosed panel (Chas. A. Peterson), *375.
Switches and switching:
——Power bus from scrap material (James P. Marshall), 409.
——Remodeling two-way switches for three-way use (Chas. A. Peterson), *517.
Tachometer and revolution counter, accuracy of (D. W. Blakeslee), (Edward A. Gibbs), 501.

T

Testing and tests:
——Ammeter leads that facilitate testing James P. Marshall), 258.
——Ball bearing lineshafts, details of (H. R. Reynolds), *62.
——Industrial plant equipment (E. S. Lincoln), *403.
——Portable-meter connections for light-load testing, *426.
Tractors (see Trucks).
Trade Literature you Should Know About, 52, 104, 164, 216, 268, 328, 380, 432, 484, 536, 600, 652.
Transformers:
——Connecting single-phase transformer to three-phase supply (Rudolph Erickson), (Earl R. Witzel), *478: (C. O. Von Dannenberg), *500.
——Protecting small transformers from shorts and overloads (J. F. Morgan), (C. Otto Von Dannenberg), 421.
——Reconnecting transformers, increasing power output by (Harry J. Achee), 257.
Transmission of power (see Belts, Chains, Clutches, Couplings, Gears, Motor drive, etc.).
Transportation (see Handling materials, Trucks).
Trucks, electric (see also Handling Materials).
——Meat Packing Plant Rivals Railroads in its Transportation Facilities (Harold J. Payne), *82.
Trucks:
——New ways to improve plant conditions with electric trucks and tractors (C. B. Crockett), *297.
——Special platform widens the field of the lift truck (G. E. Squier), *624.

U

Unemployment:
——Modern Machinery and, 203.

V

Vehicles (see Trucks).
Ventilation:
——Heating and ventilating practices at Ford plants (Fay Leona Faurote), *434.
——Pictorial section, *451.
——Preventing damage to product by fine dust (T. H. Arnold), (K. D. Hamilton), 256.
——Requirements of, for process work (C. A. Booth), *166.
——Ventilator duct easily made by gas welding (W.I.G.), *611.
——Winter-time, a need for every plant (A. P. Darling), *2.
Voltage, regulation of three-phase system (F. J. Champlin), (E. R. Wolfert), (C. Otto Von Dannenberg), *94.
Voltmeter (see under Meters).

W

Waste:
——Feeding the Octopus, *200.
Welding:
——Arc:
Angle iron arc-welded guard (Harry Gouser), *498.
Arc welded coat rack, *374.
Reconditioning plant equipment with an electric arc welder (Thomas R. Berg), *479.
Saving foundry, pattern, and fabricating costs with electric arc welding (W. G. Wehr), *19.
——Checking the welders by procedure control methods (H. E. Rockefeller), *239.
——Effect of correct materials on welding operations, the (H. E. Rockefeller), *351.
——Gas:
Gas welding procedure (H. E. Rockefeller), *507.
Odd-shaped ventilator duct made by gas welding (W.I.G.), *611.
——Truck for acetylene outfit, easily constructed (L. M. Jordan), 323.
——Unique bracing method insures rigidity in flat-bottom tank (W. I. Gaston), *612.
Wheels and casters for noiseless trucking, 224.
Winding, motor (see Motor reconnection).
Window washing in cold weather, alcohol facilitates (E.D.F.), 611.
Wire (see Cable and Wiring).
Wiring (see also Wire).
——Keeping foreign objects out of conduit (Chas. A. Peterson), *425.
——Size of conductor in three-phase circuit (G. H. McKelway), (C. O. Von Dannenberg), 320, (E. J. Morrissey), 478.
——Water-soaked cable jacked out of conduit (H. G. Millican), 480.
——Wiring trough (L. R. Bogardus), *249.
Worm gears (see under Gears).
Wrench Repair Department Saves Money (Donald A. Hampson), 425.

AUTHORS' INDEX

A

ACHEE, Harry J. Increasing power output by reconnecting transformers, *257.
Anderson, L. C. Winding data for old induction motor, 476.
Arey, H. A. Light drive power distribution, *545.

B

BANTAU, J. W. What causes blowing of fuses on transformer bank? *48.
Beck, W. A. Layout of the electrical repair shop and its methods of servicing continuous process equipment, *289.
Berg, Thomas R. Reconditioning plant equipment with an electric arc welder, *479.
Blakeslee, D. W. Accuracy of tachometer and revolution counter, 501.
Bogardus, L. R. Wiring through, *249.
Booth, C. A. Describes some of the requirements of ventilation for process work, *166.
Bowen, Russell H. What to look for when inspecting lineshaft drives, *150.
Bracken, C. E. Layout of power drives in a forging plant, *569.
Braymer, D. H. Laying out and making pulled coils, *65.
Brewer, Allen F. Filtered air as an aid to effective lubrication, *459.
——Low-temperature lubrication, *9.
——Modern lubrication practice in the steel mill, *294.
——Selecting lubricants, *125.
Brown, C. E. Built-in motors, *41.
Brown, H. J. Control equipment, *627.

C

CARBAT, SAMUEL. How can bearings be made to run cool?, 421.
Carter, Edward D. Will this ground cause trouble?, *477.
Champlin, F. J. Voltage regulators on three-phase systems, *94.
Clark, P. H. and Otis, A. N. Electrically heated melting pots for soft metals, *177.
Clements, M. E. Protecting the worker against dangerous dusts, *470.
Cole, L. A. New stator windings for old, *385.
Comer, Phil D. Method of stopping motor when pump loses suction, 159.
——What causes blowing of fuses on transformer bank?, *48.
Cook, Frank P. Systematic maintenance, *591.
Cook, N. How to determine accuracy of watthour meters, 157.
Corey, J. W. Describes some types of reversing motor drives, *362.
Crockett, C. B. Electric trucks and tractors, *297.
Cushman, A. A. Short-center drive requirements, *563.

D

DALTON, H. H. Save space and maintenance by revising power drives, *585.
Dent, H. C. Storekeeping methods for handling maintenance tools and supplies, *147.
Darlington, A. P. Winter-time ventilation, *2.
Desh, H. D. Illumination on a trial basis, *194.
Dickinson, Ernest. What causes blowing of fuses on transformer bank?, *48.
Drake, Robert W. Maintenance scheduling, *439.
——Size of equalizer required between generators, 502.
Driver, L. E. Systematic structural maintenance and repair, *383.

E

EMERSON, GRADY H. Condenser across terminals reduces lamp breakage, 375.
——Drying out water-soaked generator coils, *258.
Emerson, Grady H. (Cont.):
——Heating of motor traced to defective soldering, 516.
——Pumping unit controlled by interconnected float switch, *425.
Emerson, R. F. Conveyor drive selection, *607.
——Electrical equipment for coke plants, *307.
——Fitting the conveyor to the job, *243.
——Locating short-circuited coils, *607.
Erickson, Rudolph. Connecting single-phase transformer to three-phase supply, *478.

F

FAIRALL, E. L. Signal flags speed-up materials handling traffic, *606.
Farrer, L. I. Repairing a lift magnet, *518.
Faurote, Fay Leone. Heating and ventilating practices at Ford plants, *434.
——Maintenance practices at the Fordson plant, *107.
Finch, R. H. Automatic starting of motors after failure of power, 423.
Fisher, H. D. Layout of belt drive for waterwheel driven generator, 95.
Forger, Archie L. Inspection of electric elevator cables, 158.
Foster, V. S. Winding data for old induction motor, 476.
Fredrickson, Wm. H. Test panel for repair shop, *372.

G

GALLANT, J. H. Ball bearings on plain bearing motors, *510.
Gaston, W. I. Unique bracing method insures rigidity in flat-bottom tank, *612.
Gealy, E. J. How service requirements influence pump selection, *227.
Gibbs, Edward A. Accuracy of tachometer and revolution counter, 502.
Gibson, F. M. The plant engineer's forum, *317, *368, 418, *472, *490, *548, *634.

*Indicates illustrated articles

APR 22 29 U OF M BINDERY
434491

Girten, J. F. Operating trouble eliminated by starting motor slowly, 96.
Golladay, L. R. Lightning Arresters, *221.
Gouser, Harry. Angle iron arc-welded guard, *498.
Gratiot, J. Method of straightening crane collector bar, *612.

H

HAMILTON, JAMES T. Life of motor coils increased by dipping and baking, *210.
Hamilton, K. D. Announcing the winners in the "better system in use" contest, 153.
——Plant engineers code, 16.
——Underground distribution systems, *169.
Hampson, Donald A. Driving double-purpose blower at two speeds, *98.
——Increasing pulley diameters made drive pull load, *321.
——Lengthening a drill shank, *259.
——Suggestions on inspection of elevator cables, 612.
——What keeps the "little fellow" going?, *474.
——Wrench repair department saves money, 424.
Harman, John J. Low maintenance pipe, valves and fittings, *185.
Harte, James A. Fire protection is fire prevention, *25.
Haseltime, W. E. Nuggets from the junk pile, 611.
Henschel, Ottomar H. How to correct low power factor, *602.
Hewlett, F. G. Layout of belt drive for water-wheel driven generator, 95.
——The other side of the picture, *491.
Hogan, E. L. Present-day air-conditioning practices, *447.
Housley, J. Elmer. Color for the plant, *225.
——Fastening rotor bars to end rings, 95.
Hubbard, Charles L. Heating the small plant, *495.

J

JACKSON, J. A. Stop that waste! *443.
James, H. D. Automatic acceleration, *12.
——Maintenance of Control Equipment, *144.
Johnson, V. E. Defective commutation, *231.
——Describes the elements of commutation, *173.
——Maintenance of commutators and brushes, *365.
Jordan, L. M. Easily constructed truck for acetylene outfit, 323.

K

KAELIN, HENRY. Changing 120-volt series motor to 220-volt shunt type, 99.
Kakilty, A. W. Simple rules for laying out industrial lighting systems, *337.
Kendall, W. Tank for oil hardening small work, *259.
Kenyon, A. F. A. I. & S. E. E. holds annual technical session, 23.
Kift, D. B. Saving floor space and trucking with assembly conveyor, *360.
Kneeland, R. F. Rearranging power cables, *617.
Kopprasch, A. H. Practical pointers on armature baking ovens, *354.

L

LAABS, E. H. Adjusting double-reduction chain drive, *47.
——How magnetic brakes relieve the strain of quick stopping, *246.
Labadie, E. F. Raising the level of artificial illumination, *524.
Lees, W. Thomson. Organizing mechanical maintenance for Armco's continuous process mill, *277.
——Making the power transmission system keep pace with intensified production demands, *581.
Lincoln, E. S. Testing industrial plant equipment, *403.
Luckiesh, M. Expedite lighting maintenance, *113.

M

MACAULEY, R. G. Portable storage battery use and abuse, 611.
Mailhos, N. H. Compound winding of d.c. generators, 422.
Marshall, James P. Ammeter leads that facilitate testing, 258.
——Power bus from scrap material, 409.
Mawhennie, Edgar. Shooting three-phase four-wire trouble, 516.
McLenegan, D. W. What it pays to know about control equipment for synchronous motors, *333.
Millican, H. G. Reconnecting lighting layout for changed service, *375.
——Water-soaked cable jacked out of conduit, 480.
Millspaugh, J. W. Building for the future, *54.
Monroe, L. S. Automatic pump control, *527.
Moore, Roy C. Power belt ratings under unusual operating conditions, *389.
Moore, Roy C. (Cont.):
——Quality factors of leather belts, *29.
Morgan, J. F. Combination ground detector and alarm, *517.
——Grounded fuse clip cause of operating trouble, 158.
——Protecting small transformers from shorts and overload, 421.
Morrissey, E. J. Construction details of a low-water alarm on depth board, *518.
——Size of conductors for three-phase circuit, 478.
——Undersized motors on grinder cause of trouble, 261.
Muir, R. C. What relief for the overloaded system?, *76.
Munch, C. H. Electrical repair shop, *392.
Murray, J. S. Maintenance Stores, *395.

N

NICOLLS, J. W. Wanted—an electric oven that would run itself, *462.

O

OTIS, A. N. Electrically heated melting pots for soft metals, *177.

P

PENNY, F. H. Direct drive motors, *513.
Packer, Hall. How Armco trains its men to think and act safety, *281.
Parker, M. C. Lubricant for high temperature, 500.
——Waterproofing concrete wall, 373.
Payne, Harold J. Meat packing plant transportation facilities, *82.
Peterson, Chas. A. Auxiliary switches on discharge valves control pump motor circuits, *480.
——Keeping foreign objects out of conduit, *425.
——Remodeling two-way switches for three-way use, *517.

R

REICH, O. D. Making the power transmission system keep pace with intensified production demands, *581.
Reid, Kirk M. Trends in illumination of industrial plants, *486.
Rennick, Walter M. Locating short-circuited coils in a.c. motors, 500.
Reynolds, H. R. How much power will ball bearings save on lineshafts?, *62.
Rich, H. S. Comments on wind and whiskers, *156.
Risser, W. S. Remote control as an aid to production, *503.
Roantree, T. C. Comments on "application of gears and speed reducers on motor drives," 98.
Rockefeller, H. E. Checking the welders by procedure control methods, *239.
——Gas welding procedure, *507.
——The effect of correct materials on welding operations, *351.
Roe, A. C. Bringing obsolete motor windings up to date, *311.
——Can the speed of this motor be changed without rewinding?, 478.
——Concentric chain windings for open slot machines, *467.
——Field and armature coils, *22.
——How does increase in frequency affect core iron?, 422.
——Laying out and making pulled coils, *65.
——Layout and winding of pulled coils, *181.
——Location of phase-coils in a.c. wave windings, *629.
——Modern coils and windings, *343.
Rogers, E. F. Winding data for old induction motor, 476.
Rogers, R. H. Replacing the misfit a.c. motors, *117.
Rona, Joseph. Layout of panel for testing a.c. and d.c. equipment, *373.

S

SCHAPHORST, W. F. Gasoline engine efficiency determined from explosion count, *260.
——Selection of pulleys and belts, 422.
Schoeffler, F. Ball bearings on lineshafts, *561.
Schultz, H. L. Systematic inspection and service for low pressure fuel oil systems, *196.
Schumb, M. T. Adding life to gear drives, *111
Scott, B. W. Relation between power factor and coal pile, 421.
Sheeler, Roy C. Maintenance painting on an engineering basis, *340.
——Inspection of painted surfaces, *121.
Shultz, C. L. A simplified method of controlling maintenance stores, *395.
Sigel, E. E. What causes blowing of fuse on transformer bank?, *48.
Small, Theodore M. How can these bearings be made to run cool?, *477.
Spath, Vinzens. Commutation, 517.
Squier, G. E. The special platform widens the field of the lift truck, *624.
Spitzer, J. Locating short-circuited coils in a.c. motors, 500.
Stafford, H. E. Safe operating temperatures for magnet coils, 501.
Staniar, William. Finding the best belt for severe drive conditions, *540.
——Hidden loss reduction in mechanical power transmission, *218.
——Power transmission association, 37.

T

TAYLOR, C. STANLEY. Brighten up the dark days, *633.
Thomas, R. M. Effective gravity stop for chain conveyor, *426.
Tournier, Edward J. Are you making full use of your platform lift trucks?, *485.
——Assembly conveyors, *191.
——Better drives have improved mechanical handling efficiency, *493.
——Cut handling costs in the modern foundry, *301.
——Materials handling equipment, *141.
——Odd shapes and sizes and no obstacles to mechanical handling, *357.
——Special problems in handling materials, *415.
——Straight-line conveyor applications, *5.
——Tractor-trailer trains afford a flexible system, *614.
——What price handling building materials?, *57.
Tuck, Davis H. Lighting of high bays in industrial plants, *61.
Turner, R. B. How to locate faulty fuses on three-phase motors, 96.

V

VAN BIBBER, P. T. Describes a positive box-counting device for gravity conveyors, *189.
——Slow-speed motors, *530.
Van Brunt, G. A. How Armco handles electrical maintenance work, *273.
Van Deventer, John H. Continuous process methods multiply maintenance responsibilities, *271.
Von Dannenberg, C. Otto. Connecting single-phase transformer to three-phase supply, *500.
——Protecting small transformers from shorts and overloads, 421.
——Voltage regulators on three-phase systems, *94.
——Will this ground cause trouble?, *477.

W

WALTZ, R. D. Cost of interior painting in mill-type building, 47.
Warner, W. E. Compressed air used to remove cause of excessive sparking, 306.
——Corrosion of lead sheathed cables, 68.
——Fastening rotor bars to end rings, 95.
——Inspection in damp atmosphere cause of condenser failure, 257.
——Loose motor lead caused excessive current demand, 157.
——Raising hot water with centrifugal pump, 502.
——Selection of pulleys and belts, 422.
Weckstein, S. M. Keeping the bearings on the job, *133.
——Load and power tests on anti-friction bearings, *304.
Wehr, W. G. Electric arc welding, *19.
West, D. C. Unattended operation for industrial substations, *330.
Westbrook, Francis A. Bringing the stone-crushing plant up-to-date, *79.
——Prevention or first aid?, *130.
Wheeler, D. I. Careful attention overcomes bad operating conditions, *98.
White, Garret. Shank extension for deep-hole drilling, *480.
White, K. M. Adapting 220-volt compensator to 440 volts, *96.
——Determining width of belts from alignment chart, *261.
Wilson, S. F. Handy soft hammer made from pipe fittings, *613.
Wilson, W. D. Cutting out motor coils preferred to rewinding, 613.
Winn, J. F. Driving adjustable spindle from fixed position motor, *322.
Wisinski, Joe F. How to solder rotor clips without an iron, *425.
Witzel, Earl R. Compound winding of d.c. generators, 422.
——Connecting single-phase transformer to three-phase supply, *478.
Wolfert, E. R. Voltage regulators on three-phase systems, *94.

Z

ZIEGLER, WILLIAM G. Good plant housekeeping, *406.
——Stop that waste! *73.
——What preparation for the upkeep of plant structures?, *127.
Zimmerman, Jesse M. How motor service dictates commutator assembly, *410.
——The commutator assembled, *455.

*Indicates illustrated articles